



SERVICE INFORMATION

FROM: SERVICE DEPARTMENT

DATE: January 14, 1974

NO: D-74-15-1

Electric Tractor
EGT 120 - Lot LT 3 to 7
EGT 150 - Lot LT 4 to 8

Belt breakage on electric lift

MACHINE AND MODEL

SUBJECT

We have had several reports with problems on EGT 120 and EGT 150 tractors with the electric lift mechanism.

To help correct these problems, several recommendations must be followed.

On tractor Lots LT 3 and 4, refer to Page 12, Figure 14 of L 1001 Operator's Manual. Remove the 30 AMP fuse from the lift circuit and replace it with a 10 AMP - type 3AG automotive fuse 1-1/4" long.

On tractor Lots LT 7 and 8, refer to the same page and figure as above. Remove the 20 AMP fuse from the lift circuit and replace it with a 10 AMP - type 3AG automotive fuse 1-1/4" long.

These fuses can be obtained from automotive stores or from some service stations.

TO AVOID FUTURE PROBLEMS, THE PURCHASER SHOULD BE ADVISED THAT WHEN OPERATING THE POWER LIFT, IT SHOULD BE SHUT OFF BEFORE THE ATTACHMENT REACHES ITS UPPER LIMIT.

RO:ip